Oil Field Environmental Incident Summary

Responsible Party: Encore Energy Partners Operating LLC

Well Operator: ENCORE ENERGY PARTNERS OPERATING LLC

Well Name: FEDERAL 5-33A

Field Name: TREE TOP Well File #: 6992

Date Incident: 2/15/2014 Time Incident: 00:33 Facility ID Number:

County: BILLINGS Twp: 143 Rng: 100 Sec: 33 Qtr: SW NW

Location Description:

Submitted By: clay Booth Received By:

Contact Person: Bart Brinkerhoff

Box 569

Powell, wy 82435

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike Unknown Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	0	barrels	0	barrels			
Brine	12	barrels	12	barrels	11.5	barrels	
Other	0	barrels	0	barrels			

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/7/2014 Clean Up Concluded: 2/25/2014

Risk Evaluation: no immediate risks.

Areal Extent:

yes

Potential Environmental Impacts:

none. Area will be washed and soil replaced if necessary.

Action Taken or Planned:

Install vibration dampeners on Triplex pump. Install cement anchor to piping so no vibration can occur.

Wastes Disposal Location: Back into 5-33s holding tanks.

Agencies Involved: USDA Forest Service-Medora

Updates

Date: 5/12/2014 Status: Reviewed; USFS Lead Staff: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location valve/piping leak remained on location according to the report. USFS retains oversight.